

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
1.	BK-01/78 SZD-48 "Jantar Std 2"	SZD-48 gliders of Fact. Nos W-846, W-848, W-852, W- 854, W-857	1. Change in Technical Service Manual. 2. Change in horizontal tail plane unit.		
2.	BE-02/78 SZD-48 "Jantar Std 2"		Additional pages for Manual connected with installation of transceiver RS-6101/1.		
3.	BE-03/78 SZD-48 "Jantar Std 2"		Modification of SZD-48 glider to SZD-48-1 and connected with this extension of the flight limitations /V _{NE} from 250 km/h to 280 km/h/.		
4.	BK-04/79 SZD-48 "Jantar Std 2"	Copy with perspex opened upwards.	Replacement of pages in Manuals: 1. Technical Service Manual, Issue I - May 1978. 2. Flight Manual, Issue I - May 1978.		
5.	-	-	-	-	Item used as BE- 05/78 JANTAR STD SZD-41A
6.	-	-	-	-	As above, used as BE-06/41A/79 SZD- 41A Jantar Standard
7.	BE-07/79 "Jantar"	Glider types mentioned below: SZD-37x, SZD-38, 38A, SZD-41, 41A, 41B, SZD-42, 42-1, 42-2, <u>SZD-48</u> and <u>SZD-48-1</u>	Lacquer removal from the spar root end and root rib, then painting with colourless lacquer.	Introduce during nearest pause in flying.	
8.	BE-08/79 "Jantar Std"	Glider types mentioned below: SZD-41, 41A <u>SZD-48</u> and <u>SZD-48-1</u>	Change of life-time up to 1500 flying hours and relevant to these inspections.	After completing of previous established flying hours of after 6 years of operation.	
9.	-	-	-	-	Item used as BR- 09/80 JANTAR
10.	BK-10/80 SZD-48-1 "Jantar Std 2"	Glider types: SZD-48 and SZD-48-1	Incorporating of balancing weights at instrument panel.	At User's need.	
11.	BA-011/81 "Jantar"	Glider types mentioned below: SZD-37x, 37, SZD-38, SZD-38A, SZD-41, 41A, 41B, <u>SZD-48, 48-1</u> and SZD-49	1. Inspection of rudder lower fitting. 2. Replacement of the standard safety pin with the special safety pin securing the rudder. 3. Strengthening of the central rib in stabilizer. 4. Inspection of the elevator sandwich coverings condition.	Introduce at once.	
12.	-	-	-	-	Item used as BK- 012/81 JANTAR 2

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
13.	-	-	-	-	Item used as BE-013/81 JANTAR
14.	-	-	-	-	Item used as BK-014/81 JANTAR
15.	BK-015/81 "JANTAR"	SZD-37X, SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, SZD-42, SZD-42-1, SZD-42-2, up to B-1126 incl. <u>SZD-48, SZD-48-1</u> up to B-1195 incl. and SZD-49	Securing of the instrument panel cover against the unintentional shifting out of the fixing.	Introduced after receipt this Bulletin.	
16.	BR-016/81 "JANTAR"	Below listed glider types: SZD-37, SZD-38, SZD-38A, SZD-42, 42-1, SZD-42-2, <u>SZD-48</u> (Fact. Nos from W-846 to W-890) and SZD-48-1 Fact. Nos from W-891 to W-926, from B-985 to B-1064, from B-1095 to B-1124, from B-1135 to B-1274.	Replacement of the bolts connecting the aileron control lever in wing with aileron.	The change described in the Bulletin shall be introduced up to 30 Sept. 1983.	
17.	BI-017/82 "JANTAR"	Below listed glider types: SZD-37, SZD-38, SZD-38A ₂ , SZD-41, SZD-41A, SZD-41B, SZD-42, 42-1, SZD-42-2, <u>SZD-48</u> and <u>SZD-48-1</u> .	The list of issued Bulletins for Jantar gliders updated condition on day April 30, 1982	To be dealt as the information.	
18.	-	-	-	-	BA-018/83 "Jantar-2B" concerns: SZD-42-2 only.
19.	BK-019/83 "JANTAR"	Below listed glider types: SZD-37x, SZD-38, SZD-38A ₂ , SZD-41, SZD-41A, SZD-41B, SZD-42, 42-1, SZD-42-2, <u>SZD-48</u> and <u>SZD-48-1</u> .	Replacement of compensation volume fastening clamps in the instrument panel.	Bulletin recommended by the producer. The way of introducing is left for the user's decision.	
20.	-	-	-	-	BE-020/83 "JANTAR Std 3" Concerns SZD-48-3 only.
21.	-	-	-	-	BE-021/84 "JANTAR Std 3" Concerns SZD-48-3 only.

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
22.	-	-	-	-	BE-022/85 "JANTAR Std 3" Concerns SZD-48-3 only.
23.	BE-023/85 "JANTAR Std"	Gliders of SZD-48, SZD-48-1 and SZD-48-3 types.	Revisions in Flight Manual (it is not recommended to use the TOST EUROPA G 72 hook (with self-release) as the front hook for aerotowing).		
24.	-	-	-	-	BE-024/85 "JANTAR-2B" concerns SZD-42-2 only.
25.	-	-	-	-	BE-025/85 "JANTAR Std 3" Concerns SZD-48-3 only.
26.	BE-026/86 "JANTAR STD"	Below listed glider types: SZD-41 (X-123), SZD-41A of Fact. Nos from B-628 to B-693 (except of gliders B-702 and B-703 respected separately), <u>SZD-48, SZD-48-1 and SZD-48-3.</u>	Extension of the life-time from previous 1500 into actual 3000 flying hours for the following glider types: SZD-41 and SZD-41A „JANTAR Std”, SZD-48 and SZD-48-1 "JANTAR Std 2" SZD-48-3 "JANTAR Std 3"	To be introduced obligatory when this Bulletin is received.	
27.	BE-027/86 "JANTAR"	Below listed glider types: SZD-38A, SZD-41A, SZD-42-1, SZD-42-2, <u>SZD-48, SZD-48-1 and SZD-48-3</u> (does not concern SZD-37 (X-105)).	Extension of life-time for cables with metal core for rudder control system of Jantar gliders	The Bulletin is obligatory from the date of issue (receipt).	
28.	-	-	-	-	BE-028/87 "JANTAR 1" concerns SZD-38A only.
29.	BE-029/87 "JANTAR"	Below listed glider types: SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, <u>SZD-48, SZD-48-1 and SZD-48-3.</u>	Additional securing of the bolt connecting the tailplane with the fin against the automatic disconnection.	Acc. to user's decision.	In the course of preparation.
30.	-	-	-	-	BE-030/87 "JANTAR-2B" concerns SZD-42-2 only.

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
31.	-	-	-	-	BE-031/87 "JANTAR-2" concerns SZD-42, SZD-42-1 and SZD-42-2.
32.	BR-032/87 "JANTAR"	Below listed glider types: SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-42, 42-1, SZD-42-2, <u>SZD-48, SZD-48-1, SZD-48-3</u> and SZD-48-3M.	Compensation of plays in wing-to-fuselage connection /or middle wing-to-wingtip/ of Jantar sailplanes family.	In case the "excessive" plays appear, as defined in the Bulletin, obligatory to be introduced.	
33.	BR-033/88 "JANTAR Std 2"	Gliders: <u>SZD-48, SZD-48-1</u> "JANTAR Std 2" Fact. Nos from W-846 to W-926, from B-985 to B-1064, from B-1095 to B-1124 and from B-1135 to B-1274.	Checking for the collision of the trimming spring and cockpit floor and consequent correction of the trimming spring arm length (concerns the gliders SZD-48 and SZD-48-1).	Immediately when this Bulletin is obtained.	
34.	-	-	-	-	BE-034/88 "JANTAR Std" concerns: SZD-41, SZD-41-1 (SZD-41A), and SZD-41B.
35.	BE-035/88 "JANTAR Std 3"	Gliders: SZD-48-3 "JANTAR Std 3" Fact. Nos B-1275 and higher and two gliders SZD-48-1 "JANTAR Std 2" Fact Nos <u>B-1266 and B-1268</u> .	Revision of life-time of the gliders SZD-48-3 Jantar Std3 and two gliders SZD-48-1 Jantar Std 2 of fact. no B-1266 and B-1268.	Acc. to user's decision.	
36.	-	-	-	-	BE-036/89 "JANTAR-1" concerns SZD-38A only.
37.	BE-037/89 "JANTAR Std"	Below listed glider types: 1) SZD-41A Fact. Nos from B-628 to B-933 (except of B-700 to B-703 respected separately). 2) <u>SZD-48 and SZD-48-1</u> Fact. Nos from W-846 to W-890; from W-891 to W-926; from B-985 to B-1274 (except of B-1266 and B-1268 gliders).	Possible life-time extension above 3000 flying hours for the gliders of: SZD-41A, SZD-48-1 types.	Acc. to user's decision.	

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
38.	-	-	-	-	BR-038/89 "JANTAR 2B" concerns SZD-42-2 only.
39.	-	-	-	-	BE-039/89 "JANTAR 2" concerns:SZD-42-1 and SZD-42-2.
40.	BE-040/90 "JANTAR"	Below listed glider types: SZD-38A, SZD-41A, SZD-42-1, SZD-42-2, <u>SZD-48</u> , <u>SZD-48-1</u> and SZD-48-3.	Replacement of the driving pin of the claw-coupling body in the automatic control system connection of the Jantar family gliders.	Acc. to user's decision.	
41.	BI-041/90 "JANTAR"	All types of "JANTAR" family gliders.	Actualization of "List of Bulletins issued up to date for Jantar family gliders' (status on 31 May 1990)	To be dealt as the information.	
42.	-	-	-	-	BE-042/92 "JANTAR Std 3" Concerns SZD-48-3 only.
43.	BE-043/92 "JANTAR"	Bulletin covers these sailplanes of "Jantar" family where the ball bearings have been used as the rollers of the push-rod guides, which contact the push-rod (metal on metal). It is used in the sailplanes of SZD-48-1 "Jantar Std 2", SZD-48-3 "Jantar Std 3" and SZD-42-2 "Jantar-2B" type.	Appreciation of wear degree of the push-rod duraluminium tube surface in the location of contact with the ball bearing being used as the guiding rollers in the guides.	As necessary.	
44.	-	-	-	-	BE-044/93 "JANTAR Std" concerns SZD-41, SZD-41A and SZD-41B types.
45.	BE-045/93 "JANTAR"	All Jantar gliders: SZD-37x, SZD-38, SZD-38A, SZD-42, 42-1, 42-2, SZD-48, 48-1, 48-3 SZD-41, 41A, 41B, 41-1.	Cancellation of every 6 years inspection for all types of Jantar and Jantar Standard gliders.	Obligatory when this Bulletin is received.	
46.	-	-	-	-	BE-046/95 "JANTAR" concerns SZD-42, SZD-42-1 and SZD-42-2 type.

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
47.	-	-	-	-	NOT ISSUED
48.	BE-048/96 "JANTAR Std"	All gliders of SZD-48, SZD-48-1, SZD-48-3 type.	Wing modification, detachable wing tips with winglet.	Acc. to user's decision.	